

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565


1/6

FIG 1A



T00141544 T00141545


FIG 1B



Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565

2/6

FIG 1C



10001514-3-0101

FIG 1D





FIG 2

PRIOR ART


10004644-10101



Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565

4/6


FIG 3



Inventor(s): Huang
Serial No.: To Be Assigned
Filed: Herewith
For: Chamber-Reversed Dry Etching
Attorney Docket No.: 67,200-565

5/6

FIG 4A



સાધુવાની પત્રિકા

FIG 4B




FIG 5

